


King salmon lies dead in creek channel that was flowing two hours earlier. 11/28/97.



ACWD employee removes king salmon from channel. ACFCF weir is behind him. ACWD diversion fabric dam #1 is directly upstream of the weir. 11/28/97.

PROJECT: _____

SUBJECT: _____

11-28-97



4 FT BUT CONTACT